

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-010268**Date Inspected:** 13-Nov-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Chen Ying Xin**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

Bay 11 Spare Strut

This QA inspector performed Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT reports for this date. The members are identified as Tower Components. The weld designations reviewed are as follows.

WD1-A6003-5 Green Tag No. 9291

Out side Yard North Tower Lift 3 A/E Corner Seam (Excluding Double Diaphragm Area)

This QA inspector performed Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT reports for this date. The members are identified as Tower Components. The weld designations reviewed are as follows.

NSTL3-3B/K-84A

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This Quality Assurance (QA) Inspector observed the following work in progress:

Bay 10

SMAW welding of weld joint 1A located on ED1-SA3-18-89M-1.

Welder is identified as 052930. ZPMC CWI is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-3211-Tc-U5b-1.

SAW welding of weld joint 1A located on SD1-SA3-16-89M-1.

Welder is identified as 052917. ZPMC CWI is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-3221-Tc-U5-S-1.

SMAW welding of weld joint 39 located on ND1-A6002-17.

Welder is identified as 056364. ZPMC QC is identified as Mr. Yuan Hui Gang.

The welding variables recorded by QC appeared to comply with WPS-B-T-2113.

FCAW welding of weld joint 1A located on SSD1-SPSA4-22.

Welder is identified as 048627. ZPMC CWI is identified as Mr. Gong Liang Zhu.

The welding variables recorded by QC appeared to comply with WPS-B-T-2231-Tc-U5-F.

SAW welding of weld joint 8A located on SSD1-TL5-1C-F.

Welder is identified as 040252. ZPMC CWI is identified as Mr. Du Zhi Qun.

The welding variables recorded by QC appeared to comply with WPS-B-T-3221-B-U3c-S-1.

FCAW welding of weld joint 2A located on NSD1-SPSA4-22.

Welder is identified as 066733. ZPMC CWI is identified as Mr. Gong Liang Zhu.

The welding variables recorded by QC appeared to comply with WPS-B-T-2231-Tc-U5-F.

SAW welding of weld joint 7A located on NSD1-TL5-3C-F.

Welder is identified as 209051. ZPMC CWI is identified as Mr. Du Zhi Qun.

The welding variables recorded by QC appeared to comply with WPS-B-T-3221-B-U3c-S-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 134-8257-0045, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By: Gaikwad,Umesh

Quality Assurance Inspector

Reviewed By: Clifford,William

QA Reviewer